

Message

From: Smallbeck, Donald R. [donald.smallbeck@woodplc.com]
Sent: 7/19/2018 2:52:24 PM
To: 'JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW' [catherine.jerrard@us.af.mil]; 'Wayne Miller' [Miller.Wayne@azdeq.gov]; d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]; Pearson, Stuart C. [stuart.pearson@woodplc.com]
CC: d p [DPope@css-dynamac.com]; Davis, Eva [Davis.Eva@epa.gov]; 'MOOK, PHILIP H JR GS-15 USAF AFCEC AFCEC/CIBW' [philip.mook@us.af.mil]; 'Geoff Watkin' [Geoff.Watkin@SpecProSvcs.com]; Nicole Goers [Nicole.Goers@TechLawInc.com]; 'Brasaemle, Karla' [KBrasaemle@TechLawInc.com]; Anderson, Scott J [scott.anderson2@woodplc.com]; 'Rohrbaugh, Amanda' [ARohrbaugh@TechLawInc.com]; 'Bo Stewart' [bo@praxis-enviro.com]; 'William Hughes' [William.Hughes@SpecProSvcs.com]; 'steve@uxopro.com' [steve@uxopro.com]; 'Jennings, Eleanor' [Eleanor.Jennings@parsons.com]
Subject: ST012 Site Activities and two week look ahead

Activities Last Week

- SVE Operation
- Set up portable steps for pre-mix tank.
- Troubleshoot extraction pumps in UWBZ26, UWBZ27, and UWBZ30 (not pumping)
- Finalized HASP revisions for sodium sulfate handling
- Sampled CZ23 for VOCs
- Sulfate mixing and injection on hold
- Continued CZ07 extraction

This Week (7/16-7/20)

- SVE Operation
- LNAPL checks
- Determine ladder solution for checking EQ tank LNAPL
- Test spare pumps on VFDs
- Continued CZ07 extraction

Next Week (7/23-7/27)

- SVE Operation
- Pull and replace pumps that are not working.
- Continued CZ07 extraction

D.R. Smallbeck
Principal Program Manager
Construction Remediation

4600 E. Washington Street, Suite 600, Phoenix, Arizona 85034-1917
D +1.602.733.6040 C +1.707.480.7212
Donald.Smallbeck@amecfw.com
www.woodplc.com



Amec Foster Wheeler and Wood Group are now Wood.

This message is the property of John Wood Group PLC and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorized use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system.

If you do not wish to receive future unsolicited commercial electronic messages from us, please forward this email to: unsubscribe@woodplc.com and include "Unsubscribe" in the subject line. If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click <http://www.woodplc.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.

As a recipient of an email from a John Wood Group Plc company, your contact information will be on our systems and we may hold other personal data about you such as identification information, CVs, financial information and information contained in correspondence. For more information on our privacy practices and your data protection rights, please see our privacy notice at <https://www.woodplc.com/policies/privacy-notice>
